


ATTENCION NEW ELECTRONIC CONTROL!

Preliminary Information
Original instructions gets delivered in addition!

Electronic control „PAVOtronic“

Layout of the electronic control



Brief instructions „PAVOtronic“

1. Switch Pavotronic on and off

A short press on I/O button switches the controller on.

The display shows the adjusted working mode and the request to press a button. No hydraulic function is chosen.

The control box may be switched off by a short press on I/O button.

2. Shift from furrow ploughing to onland ploughing

Press button furrow/onland for 3 seconds.

The display shows “shift working mode!”. “New working mode xyz” appears on it.

When the button is pressed less 3 seconds the former adjustment remains. The adjusted working mode remains also after switching off.

This button allows to aborting other features, in particular zero setting.

3. Select a function

The buttons track adjustment, turn around adjustment, working width and working depth activates the respective feature.

A second press on the same button deactivates it.

A press on another button deactivates the present feature and activates the new one.

4. Zero setting

The button “zero setting” activates the development to zero setting of the plough.

Depending of the working mode an order of operations must be executed.

The display shows the current feature and a request for the next step.

A wrong press get ignored.